

## Text Concern Mitigation Planning Estimated Deficiency Safety<sup>(1)</sup> / Operation<sup>(2)</sup> Citation Plan Cost<sup>(3)</sup> Horizon GEOTECHNICAL Surface running water/drainage trench at Safety - Standard 2.1.1.1 7.2.1.1.1 Near Term 28K\$ Gate 4 **Operation** - No 3.1 Safety - Standard Sinkholes behind Lock 3 Corps Side wall 7.2.1.1.2 Near Term 44K\$ 2.1.1.2 **Operation** - No 2.1.1.1 Safety - Standard Seepage at Gate 4 Corps Side monolith 7.2.1.2.1 5-Year 1,042K\$ Operation - No 3.0 Safety - No Seepage Remediation – Alternative 1 2.1.2.3.2 7.2.1.2.2 5-Year 872K\$ Operation - No Safety - No Seepage Remediation – Alternative 2 2.1.2.3.2 7.2.1.2.3 5-Year 170K\$ Operation - No STRUCTURAL Safety - No 2.1.2.3.3 Through wall leakage, Mill Side No \_ Operation - No Access ramp foundation undermining, Safety - No 2.1.2.5.1 No downstream approach, Corps Side **Operation** - Yes Safety - No 2.2 Dredging No --**Operation** - Yes Safety - DSAC 1 2.1.2.4.2 Gudgeon anchorage system 7.2.2.1.1 Near Term 710K.\$ 6.0 **Operation** - No 2.1.2.2.3 Safety - Standard Timber brace for wall lagging 7.2.2.1.2 Near Term 3K\$ 2.2 Operation - No Safety - Standard 2.1.2.5.2 Walkway framing 7.2.2.1.3 Near Term 51K\$ **Operation** - Yes 2.2 Safety - DSAC 1 4.1.2 7.2.2.1.4 Monolith stability Near Term 663K.\$ Operation - No Safety - DSAC 1 Wall stability 4.1.3 7.2.2.1.5 Near Term 3,445K\$ Operation - No Safety - No Gate 4, Corps Side, operator support 2.1.2.4.3 7.2.2.2.1 5-Year 206K.\$ Operation - Yes Safety - No Gate 2, Corps Side, operator support 2.1.2.4.3 7.2.2.2.2 5-Year 288K.\$ **Operation** - Yes Safety - Standard Chamber ladders 2.2 7.2.2.2.3 5-Year 55K\$ **Operation** - Yes Safety - Standard 2.2 7.2.2.2.4 5-Year Guardrails 163K.\$ **Operation** - Yes Safety - Standard Lock control stand at Gate 6, Mill Side 2.2 7.2.2.2.5 5-Year 5K\$ **Operation** - Yes 2.1.2.2.1 Safety - No Loss of masonry at lowest course at the 7.2.2.3.1 Long Term 353K.\$ 2.2 Operation - No downstream approach, Mill Side Safety - No 2.1.2.2.2 7.2.2.3.2 Long Term 746K.\$ Timber facing Operation - No MECHANICAL Safety - No Gate and valve control system 2.1.3.1 No -**Operation** - Yes

## Table 7.1Deficiencies by Discipline

Gate and valve limit switches	2.1.3.7 5.1	Safety - No Operation - Yes	7.2.3.1.1	Near Term	419K.\$
Fire protection equipment	5.1	Safety - Standard Operation - Yes	7.2.3.1.2	Near Term	782K.\$
Limit switches (Second Set)	5.1	Safety - No Operation - Yes	7.2.3.1.3	Near Term	CES
Valve seals	2.1.3.5	Safety - No Operation - Yes	7.2.3.2.1	5-Year	1,625K\$
Bubbler system	2.1.3.8 2.2	Safety - No Operation - Yes	7.2.3.2.2	5-Year	176K.\$
Hydraulic cylinder	2.1.3.5 5.1	Safety - No Operation - Yes	7.2.3.2.3	5-Year	280K.\$
Miter blocks	2.1.3.3	Safety - No Operation - Yes	7.2.3.3.1	Long Term	2,183K\$

2.1.3.4

2.1.3.6

Safety - No

Operation - Yes Safety - No

**Operation** - Yes

No

No

\_

Willamette Falls Locks Evaluation Report

Debris

Bottom seal



\_



ELECTRICAL									
Electrical distribution system- conduit, conductors, enclosures, and supports	2.1.4.1	Safety - No Operation - No	No	-	-				
Remote monitoring/ operating system	2.1.4.2 2.2	Safety - No Operation - Yes	No	-	-				
Standby Generator	2.1.4.5	Safety - No Operation - No	No	-	-				
Lighting system	2.1.4.3 2.2	Safety - Standard Operation - Yes	7.2.4.1.2	Near Term	702K\$				
Gate open limit switches (2 <sup>nd</sup> set)	2.1.4.2 5.2	Safety - No Operation - Yes	7.2.4.1.3	Near Term	320K.\$				
Gate valve limit switches	2.1.4.2 5.2	Safety - No Operation - Yes	7.2.4.1.4	Near Term	50K\$				
CCTV- replace/add to provide full coverage	2.1.4.4 2.2	Safety - Standard Operation - Yes	7.2.4.1.5	Near Term	521K\$				
Gate open limit switches	5.2	Safety - No Operation - Yes	7.2.4.2.2	5-Year	426K.\$				
Control system replacement	2.1.4.2	Safety - No Operation - Yes	7.2.4.2.3	5-Year	1,532K\$				
Gate fill Valve Limit Switch- Replace All	5.2	Safety - No Operation - Yes	7.2.4.3.2	Long Term	727K\$				
CCTV- replace/upgrade all cameras with pan-tilt-zoom	2.1.4.4 5.2	Safety - No Operation - Yes	7.2.4.3.3	Long Term	1,649K\$				

(1) Safety Concern - Yes or No, (If Yes, either DSAC I or Standard)

<u>DSAC1</u> - Deficiency contributes to an urgent and compelling issue that requires taking immediate and expedited actions to reduce and manage the risk.

Standard Safety - Deficiency which adversely affects staff and visitor safety but does not present a DSAC I level concern.

(2) Operational Concern - Yes or No

(3) <u>Construction cost at mid-point of construction, in 2011 dollars Costs are fully funded and are comprised of Construction cost + contingency, plus</u> <u>E & D + E & D Contingency, plus S \& A + S \& A contingency</u>. Costs are then escalated from their effective price date to mid-point of construction for <u>Construction and S & A cost and to mid-point of design for E & D cost</u>.

Willamette Falls Locks Evaluation Report

