


Sauvie Island Drainage Improvement Company



1. A1 Canal



2. Main Pumping Plant



2. Inside Main Pumping Plant



2. Inside Main Pumping Plant



3. Sturgeon Lake



4. Typical Levee Section



5. Common Encroachment



6. Erosion on Levee along Multnomah Channel



Multnomah County Drainage District #1



1. Multnomah County Drainage District No. 1 Office & Pump Station No. 1



2. Image of MCDD
flooded in 1948



2. Troop Work on
Levee Across from
Airport in 1948

3. Levee Across from Portland Airport



4. Portland International Airport




5. 1996 High Water Event Repair



6. Marine Drive Bike Path is a Regional Recreational Asset



7. Structural Encroachments



8. West side of 142nd Cross Levee




9. Blue Lake Regional Park - Metro



10. Beaver Dams Across from
Chinook Landing Along Levee Toe



Sandy Drainage Improvement Company



1. Sandy Drainage Improvement Company Pump Station



1. SDIC Pump Station Pumps



2. Troutdale Reynolds Industrial Park



3. Northeast Side of SDIC Levee



JAN 11 2010

3. Northeast Side of SDIC Levee - Covered in Bricks



4. Toe Drain Locations



5. Eastern end of SDIC Levee

