





Frame ① 4 May 82 Gate No. 1
 Pintles for Rt & Lt. Leaves
 Pintle Bushing for Lt. Leaf




Frame ② 4 May 82
 Pintle Bushing for Rt. Leaf - 3 bolts Sheared




Frame (4) Gate No. 1
4 May 82
Left Leaf



Frame (5) Gate No. 1
4 May 82
Left Leaf



Frame (6) 4 May 82 Gate No. 1
Left Leaf



Frame (7) 4 May 82 Gate No. 1
Rt. & Left Leafs




Frame 9 4 May 82 Gate No. 1
Rt. Leaf of Barge Crane



Frame 8 4 May 82 Gate No. 1
Barge Crane



Frame (10) 5 May 82 Gate No. 1
Left Leaf - Lower end of Diagonal



Frame (11) 5 May 82 Gate No. 1
Left Leaf
Airgauged cracks



Frame (12) 5 May 82 Gate No. 1
Gouged crack Left Leaf




Frame (13) 5 May 82 Gate No. 1
Left Leaf



Frame (15) 5 May 82

Frame (14) 5 May 82

Gate No. 1 Left Leaf




Frame (17) 5 May 82


Frame (18) 5 May 82

Gate No. 1


Right Leaf



Frame 5A left leaf 11 May 1982



Frame 6A - Lifting ~~left leaf~~
left leaf for warpage
measurement. 11 May 1982




Frame 8A



Frame 7A

Left Leaf 11 May 1972



Frame 2A - Left Leaf -
Flange Repair Plate May 11, 1982



Frame 0A - Left Leaf - new diagonal
eye at lower end. May 11, 1982



Frame 3A - Left Leaf - Measuring
Line @ Lower Corner

11 May 1982



Frame 4A - Left Leaf

11 May 1982



12A

left leaf



11A

11 May 82



Frame 13A

Left Leaf

11 May 82



Frame 14A

Left Leaf


11 May 82



Frame 16

Date No. 7


21 May 1982



Frame 17



Gate No. 7
21 May 82



Gate No 7
21 May 82



①⑧ 6/17/83



①⑨ 6/17/83



Gate No. 1
Willamette Falls
Lock


11 Feb 82



11 Feb 82



11 Feb 82
Gate No. 1
Willamette Falls
Lock



11 Feb 82
Gate No. 1
Willamette
Falls
Lock





11 Feb 82
Gate No. 1
Willamette Falls
Lock

